

State Water Resources Control Board

April 29, 2016

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7015 1520 0001 8019 6682

Mr. Jerry McDonald
Shop Supervisor
Mid Placer Public Schools Transport
13121 Bill Francis Drive
Auburn, California 95603
shop@midplacer.k12.ca.us

**SUBJECT: NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS
LOCATED AT MID PLACER PUBLIC SCHOOLS TRANSPORT, 13121 BILL
FRANCIS DRIVE, AUBURN**

Dear Mr. McDonald:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on April 21, 2016, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and title 23, California Code of Regulations (CCR), chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Maintain Plot Plan/Site Map – Map does not list the sensor numbers and locations.	All	April 21, 2016	Ongoing	23 CCR 2711(a)(8)
2	Failure to Notify Local Agency of DO – The ICC certification for the DO listed on the Statement of Designated Operator form is expired.	All	April 21, 2016	Ongoing	23 CCR 2715(a)
3	Failure to Maintain Primary and/or Secondary Containment – The unleaded piping sump has a strong smell of ethanol and a heavily corroded turbine pump indicating a possible leak.	Unleaded	April 21, 2016	Ongoing	H&SC 25291(a)
4	Failure to Tag Monitoring Equipment – The line leak detectors did not have monitoring certification tags on them.	All	April 21, 2016	Ongoing	23 CCR 2638(f)

No.	Violation	Tank	Start Date	Stop Date	Regulation
5	Failure to Monitor Product Piping – The sensors in the unleaded UDC and diesel piping sump were unable to detect a leak at the earliest opportunity because they were not in a vertical position.	All	April 21, 2016	Ongoing	23 CCR 2630(d)
6	Failure to Maintain Monitoring or Testing Records On-site – Three years of testing records are required to be maintained on-site. The county inspector provided copies of the missing testing records during the inspection.	All	April 21, 2016	April 21, 2016	H&SC 25293; 23 CCR 2712(b)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and the Placer County Environmental Health Department within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

State Water Board

Ms. Rebecca Green
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
1001 I Street, 16th Floor
Sacramento, California 95814
rebecca.green@waterboards.ca.gov

Local CUPA

Mr. Nikolay Ostrovskiy
Environmental Health Tech. Specialist
Placer County Environmental Health Dept.
3091 County Center Drive
Auburn California, 95603
nostrovs@placer.ca.gov

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,



Amantha Henkel
Senior Environmental Scientist
UST Enforcement Unit
Office of Enforcement

cc: See next page.

cc: *(via email only)*

Mr. West Bourgault
Environmental Health Tech. Specialist
Placer County Environmental Health Department
wbourgau@placer.ca.gov

Mr. Nikolay Ostrovskiy
Registered Environmental Health Specialist
Placer County Environmental Health Department
nostrovs@placer.ca.gov